

IN THE DRAWINGS

Corrected drawings are supplied herewith, each labeled as "REPLACEMENT SHEET".


In FIG. 4 and FIG. 5, in block 340, the word "Synchrounous" above "Scan Control" has been replaced with "Synchronous". These changes are made to correct a typographical error and to be consistent with the Detailed Description. No new matter has been added.



TITLE: APPARATUS AND METHOD FOR ANALYSIS AND TROUBLESHOOTING OF ELECTRONIC DEVICES
INVENTOR NAME: Reuven Lovie et al.
SERIAL NO.: 10/020,200

REPLACEMENT SHEET

4/6



5/6




FIG. 5